



Ref. No. str-Cert 2021/06/23

Date 08/06/2021

CERTIFICATE OF STABILTY OF THE SECHOOL

I hereby declare that I have personally inspected the site , Examined the plans & specifications of the building described below , the heights of the roofs, the actual materials and methods used in construction and the finished building . I am satisfied that its construction is such that its stability is satisfactory and used as a School.

DESCRIPTION OF BUILDING

1. Name of the School :- ASIAN PUBLIC SCHOOL.
2. General type of construction :- B/w in cement moter, both side plaster, R.C.C. slab roof, tiles & wooden flooring ,Colour, 2 Gates doors & windows.Conduit wiring & plumbing etc.
3. Full Name of signatory :- Er. R.K. SINGH
4. Qualification :- B.E. (Civil)/ M. Tech/.
Chartered Er.
5. Name of room of building
For which the certificate granted
Give reference to plan No. :- As per attached plan.
6. Date of issue :-08/06/2021
7. Year of construction :- 2001-2002
8. Location of the School :-AT Vill. Kharoda Dauhla,
Harchander pur ,Road Gurgaon
Shona Hr.

Raj Kumar
CHARTERED ENGINEER (C ENO)
RAJKUMAR SINGH
Member of Institution of Engineers (India)
M-1562185
1192/9A, U.E. Gurgaon (Hr.)
Mob.: 9313219882, 0124-4380921